Sears House 958 Route 23 Wayne Passaic County New Jersey

HABS NJ, 16-WAYN, 3-

PHOTOGRAPHS

HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, D.C. 20240

United States Department of the Interior National Park Service Washington, D.C. 20240

HISTORIC AMERICAN BUILDINGS SURVEY


ARCHITECTURAL DATA FORM

HABS NJ. 16-WAYN, 3-


1981; 1982

STATE	COUNTY	TOWN OR VICINITY	
NEW JERSEY	PASSAIC	WAYNE	
HISTORIC NAME OF STRUCTURE (IN SEARS HOUSE	NCLUDE SOURCE FOR NAME)		HABS NO. NJ-872
SECONDARY OR COMMON NAMES OF	STRUCTURE		*
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)			
958 Route 23. The house had been moved twice before its last location.			
DATE OF CONSTRUCTION (INCLUDE SOURCE) Circa 1887 ARCHITECT(S) (INCLUDE SOURCE)			
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) The house is a typical example of an ordinary 19th century residential structure with a rectangular plan.			
STYLE (IF APPROPRIATE)			
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Wood frame structural system. Originally clapboarded, painted white. At least two kinds of exterior covering had been applied over the clapboarding; the last covering was probably of asbestos material.			
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) See attached sheet for sketched floor plans.			
EXTERIOR FEATURES OF NOTE Original windows had two-over-two double-hung sash and were shuttered. Replacement windows were one-over-one double-hung sash. The roof consisted of two intersecting gable roofs. The side roofs originally were decorated with bargeboards, which were later removed. The chimney was an alteration of an earlier one.			
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) The house had a central hall floor plan; see attached sheet for sketched floor plans. There was a stamped metal ceiling in the dining room.			
MAJOR ALTERATIONS AND ADDITION	NS WITH DATES		
PRESENT CONDITION AND USE Demolished.			
portation and the Advisory Cou	ATE a Memorandum of Agreement betwo uncil on Historic Preservation on the road improvement project	in compliance with	tment of Trans- Executive Order
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Route 23, 2D Technical Support Document, 1977			
COMPILER, AFFILIATION Bureau of Environmental Analy	ysis, N.J. Department of Transp	DATE ortation;	

Susan McCown, Historian, Historic American Buildings Survey



SEARS HOUSE HABS No. NJ-872 (page 2)



2ND FLOOR